


Forces between two infinitely long straight parallel conductors carrying currents -



consider two infinitely long parallel conductors carrying current  $I_1$  and  $I_2$  in the same direction.

The magnetic field at any point on the conductor (2) due to current  $I_1$  in the conductor (1) is given by

$$B_1 = \frac{\mu_0}{4\pi} \left( \frac{2I_1}{d} \right)$$

Force experienced per unit length of conductor (2) in the magnetic field  $B_1$  is given by

$$F_2 = B_1 I_2 \times 1 = B_1 I_2$$

$$\text{or } F_2 = \frac{\mu_0}{4\pi} \left( \frac{2I_1}{d} \right) I_2 = \frac{\mu_0}{4\pi} \left( \frac{2I_1 I_2}{d} \right)$$

Applying Fleming's L.H.R. to conductor (2), the direction of  $F_2$  is in the plane of the conductor directed towards conductor 1

$$\text{Similarly } F_1 = B_2 I_1 \times 1 = \frac{\mu_0}{4\pi} \left( \frac{2I_1 I_2}{d} \right)$$

By LHR,  $F_1$  lies in the plane of the conductor and directed towards conductor (2)

$F_1$  and  $F_2$  are equal and opposite,  
 so these forces pull the conductors  
 towards each other.

Definition of Ampere (from force experienced  
 by current carrying parallel conductors)

Force experienced per metre length of conductor

$$F = \frac{\mu_0}{4\pi} \left( \frac{2I_1 I_2}{d} \right) \text{Nm}^{-1}$$


Let  $I_1 = I_2 = 1\text{A}$   
 $d = 1\text{m}$

$$F = \frac{4\pi \times 10^{-7} \times 2 \times 1 \times 1}{4\pi \times 1}$$

$$= 2 \times 10^{-7} \text{Nm}^{-1}$$

Thus, ampere is that current which if  
 maintained in two infinitely long parallel  
 conductors of negligible c/s area separated  
 by 1m in vacuum causes a force of  
 $2 \times 10^{-7} \text{N}$  on each metre of the other  
 wire.

If current in both parallel wires is  
 equal and in the same direction then  
 magnetic at a point exactly half way bet<sup>n</sup>  
 the wires is  $B_p = B_1 - B_2 = 0$




$$B_1 = \frac{\mu_0 2I}{4\pi d}$$

$$B_2 = \frac{\mu_0 2I}{4\pi d}$$

But if the wires carry current in the opposite direction then

$$B_p = B_1 + B_2$$

$$= 2 \left[ \frac{\mu_0 2I}{4\pi d} \right]$$



current loop (circular, rectangular etc)

Torque on current carrying rectangular loop placed in uniform magnetic field.




Fig 1




Fig 2



consider a rectangular conducting loop ABCD of length  $l$  and breadth  $b$  placed in uniform magnetic field  $\vec{B}$ . Let  $I$  flows in anticlockwise direction. Let  $\theta$  be the angle bet<sup>n</sup> the normal ( $\hat{n}$ ) of the plane of the loop and the magnetic field  $\vec{B}$ .

Force acting on arm AB of the loop

$$\vec{F}_1 = I(\vec{l} \times \vec{B})$$

Applying LHR, direction of  $F_1$  is  $\perp$  to the length of arm AB and directed outward of the sheet of paper

Similarly, force acting on CD

$$\vec{F}_2 = I(\vec{l} \times \vec{B})$$

$\vec{F}_2$  is  $\perp$  to the length of arm CD and is directed inside the sheet of the paper

(Force acting on the arm BC and DA are equal, opposite and act along the same line, hence they cancel each other.

$\therefore F_1$  and  $F_2$  form a couple and rotates the loop anticlockwise

$$\tau = \text{Magnitude of either force} \times \text{lever arm} = F_1 \times DN$$

$$= I(\vec{l} \times \vec{B}) \times DN$$


$$= I(lB \sin 90^\circ) \times b \sin \theta$$

$$= I(lb)B \sin \theta$$

$$\tau = IAB \sin \theta$$

If the loop has  $N$  turns, net torque


$$\tau = NIAB \sin \theta$$



Conversion of galvanometer into Ammeter  
 with the help of shunt by connecting  
 a low resistance called shunt parallel to  
 the galvanometer

$R_G$  = Resistance of galvanometer  
 $r_s$  = shunt resistance

$I$  = Total current to  
 be measured  
 by an ammeter  
 in the circuit



$I_g$  = current flowing through the galvanometer  
 corresponding to which the galvanometer gives  
 full scale deflection.

$I - I_g \rightarrow$  flows through shunt.

$$I_g R_G = (I - I_g) r_s$$

$$\text{or } r_s = \left( \frac{I_g}{I - I_g} \right) R_G$$

This is the required  
 value of shunt resistance  
 to convert a galvanometer  
 into an ammeter of  
 range 0-I ampere

Effective Resistance of Ammeter:

$$\frac{1}{R_{\text{eff}}} = \frac{1}{R_G} + \frac{1}{r_s} = \frac{R_G + r_s}{R_G r_s}$$


$$\text{or } R_{\text{eff}} = \frac{R_G r_s}{R_G + r_s}$$

if  $R_G \gg r_s$ ,  $\therefore R_G + r_s \approx R_G$

$$\text{Hence } R_{\text{eff}} = \frac{R_G r_s}{R_G} \approx r_s$$

Thus, ammeter is a low resistance device.  
 Resistance of ideal ammeter is zero

Conversion of Galvanometer into Voltmeter:  
 by connecting a <sup>high</sup> ~~large~~ resistance in series to the galvanometer.



$R_g$  = Resistance of galvanometer

$R$  = Resistance of conductor

$V$  = potential difference to be measured by the voltmeter

P.D. bet<sup>n</sup> A and B is

$$V = I_g (R + R_g)$$

$$(R + R_g) = \frac{V}{I_g}$$

$$R = \frac{V}{I_g} - R_g$$

This is the required value of resistance which must be connected in series to the galvanometer to convert it into voltmeter of range  $0 - V$  volt

Effective Resistance :  $R' = R + R_g$ , which is high.

Resistance of ideal voltmeter is infinite.